

TechCore Windows Cleanup Card

Free TechCore utility - Safety-first reference

1. Restart before troubleshooting.
2. Open Task Manager and review CPU, memory, disk, and startup apps.
3. Keep at least 15 to 20 percent of the SSD free.
4. Run Windows Security.
5. Back up important files before major changes.

Stop for smoke, sparks, burning smells, liquid damage, or anything unsafe.